

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

-- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.


The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.


-- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.



TORQUE TUBE

THE NEWS PUBLICATION FOR MEMBERS OF THE 1937-1938 BUICK CLUB



VOLUMN XV . NUMBER 3 . JANUARY / FEBRUARY 1997

BUICK 1937 11938

NUMBER 3

RRY LOGAN #651


Happy 60th Birthday to all our 1937 Buicks

This unrestored 1937 Special Sport Coupe renew. Hopefully many of those receiving remind-Model 46S belongs to Dave Tacheny (#997) in ers will rejoin our great '37-'38 Buick Club.

Minnesota. This original car has a radio, sidemounts, heater, a spotlight and the rear folding jump seats. This second photo shows the original interior of Dave's coupe. Looks very good for a 60 year old car.

This is the January/February issue, the third of six in our 1996-1997 publishing year. Our paying membership is now 445, down from 514 last year. I've just mailed out a hundred reminder notices to those who did not





The last issue showed a photo (top of page 2) of a 1950 New York street scene with two '38 Buicks parked at the curb. I want to thank to Tony Bracken (#945) for sharing this photo with us. He commented on how much fun the children were having playing a game in the street with only a piece of chalk. How times have changed! Thanks Tony.

The full color magazine ad (bottom of page 2) shows a 1938 Special Streamline







Buicks originally cost in the neighborhood of

\$1,200. Notice the car has no bumper medallion. Buick built a little over 11,000 38-47's. Thanks to Doug Nelson (#51) for sharing this ad.

Here's a photo (top of page 3) of master mechanic Karl Anderson's (#47) shop in Berryville, VA.

That's Karl with the hat and Andy Diem (#852) convertible sedan photo for now (top of page 4).

This factory photo (second photo on page 3) shows a '38 Convertible Sedan. It is a Special Model 40C with the selfshifting transmission. Thanks to Terry Dunham for sharing this photo.

Dave Lewis (#237) our Club founder, is storing

(Slant-back) 4-Door Sport Sedan Model 47. These an unrestored '38-40C self-shifter for the owner (see bottom photo page 3). Buick made 776 38-



40C's plus another 170 for export. Incidentally, if you need an original near mint condition Self Shifting Manual(see third photo page 3). Andy Diem (#852) has one of these for sale. Call him at (202) 364-8115 Eastern Time.

Here's our last

looking on with the back of Von Hardesty's It's a maroon '37 Century Convertible Sedan (#964) maroon '37 Century Convertible show- Model 60C. All '37 and '38 Buick Convertible

Sedans were slantbacks. The photo was taken at the BCA Nationals in Los Angeles a few years ago. Thanks to Joe Giordano (#333) for sharing this photo.

What color should you paint the rear bumper gravel guards? (see middle photo on page 4) The an-



The TORQUE TUBE is published bi-monthly for the enjoyment of the 1937-1938 Buick Club. Membership dues are \$34.00 per year US, \$35.00 per year Canada and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the 1937-1938 Buick Club.

Please send all articles, ads subscriptions and inquires, etc. to:

The TOROUE TUBE 1005 RILMA LANE LOS ALTOS, CA 94022 USA

You can reach Harry Logan by PHONE/FAX (415) 941-4587 or by E-mail: harrylogan@earthlink.net

Editor......Harry Logan, #651 Art Director......Dug Waggoner, #10

Printer Liaison.....Bill Olson, #427 Printer......Conrads Printing, Lancaster, Ohio

All rights reserved. No part of this newsletter may be reproduced in any form without written permission from THE TORQUE TUBE.

swer is black, not body color. I have seen about 10 and all were black. Most were flat or dull black like this one on a '38 Special 4-Door Sedan Model 41 that still had it's original Van Gogh Green paint. I have also seen them painted gloss black on renicer, especially if the car has a new paint job. But the gravel deflector must be in excellent condition because gloss black will show up any dents or ripples in the metal.

I bought a used gravel guard and straightened


it, but it showed all the ripples when painted gloss black. Now it's painted flat black and looks better as the ripples do not stand out. Does any member have more information on the color of gravel deflectors?

Dave Powers (#894) writes that he received the last Torque

Tube just as he and his wife were leaving to go on vacation. But he grabbed the magazine and hid out until he had read most of it, then took it with him. Dave just got his '37 Roadmaster Phaeton 80C running after 2 years of work (an engine



cently restored cars. To my eyes, gloss black looks temperature. Take a pan of boiling water out to



where you are painting and place the spray can in the hot water for 3-4 minutes before spraying. After 5 minutes, reheat the can to keep the pressure up. Dave says that heating the can will increase the spray pressure,

rebuild, new brakes

and other repairs).

looking forward to

driving it in 1997.

aerosol can spray

painting. Dave

says there is never

enough pressure in spray cans so to

increase the pres-

sure, increase the

Dave says he's

One hint Dave offers deals with

causing a finer atomization of the paint. (Ed. Never place aerosol paint cans over open flame or heating element to achieve better aerosol pressure. User beware.)

Dave Paulisin (#704) in Michigan gave his "best friend, mentor and brother" (that's one person) a

subscription to the Torque Tube. Dave's

brother Bill is looking for a restored '37 or '38 Buick coupe like the one he had as a teenager. Dave and Bill are currently restoring a 1928 Graham-Paige 610 sedan exactly like the one their grandfather owned for over 30 years. His



grandmother didn't want it around as grandpa was now 90. So he sold to a kid who ruined it trying to make this mint original into a hotrod!

The February, 1997 issue (#157) of Special Interest Autos Magazine

has an excellent article on the 1938 BUICK Y-JOB (see bottom photos). This concept car was built on a 1938 Buick Century chassis. It had the 141 hp Big Series engine, at that time GM's most powerful in standard production cars. (This compares to 135 hp for the standard 1938 Cadillac V-8).

The Buick engine also carried the stylistic advantage of being longer than the Cadillac V-8, justifying a long hood. Long hoods implied power in those days. The Y-Job became Harley Earl, the head of GM's Styling Section's personal car. He put more than 50,000 miles

on it and was still driving it even after W.W.II. Many of its features such as the grille and bomb-



tion packages on Buicks for \$40.00. But he will do this for free to members who can supply him production information sheets (a Buick form called a Car Packing Slip, see example at bottom of page 5), or cars with unusual

numbers or situations. Terry can be reached at (407) 880-1258 or at PO Box 4057, Apopka, Florida 32704-4057.

Richard Parkes (#169) in Canada writes that he would like to see some old photos of factory assembly lines. Here are three (see top of page 5) from 1937 showing motor assembly, the body drop and painting. If any one has other assembly line shots, please loan them to me to share with our members in the Torque Tube.

In the May/June 1996 issue, I wrote how I check that my brake lights work using the ammeter and

stepping on the brake pedal. Charlie Ross (#1015) in Warwick, RI checks his by watching

their reflection on the white surface of his overhead garage door while looking in the rear view mirror. A burnt out bulb will cause that sides reflection to be dimmer than the working one.




sight hood ornament were used in later Buicks. What I wouldn't give to drive into the Buick National Meet next July with this masterpiece!

Buick historian and author Terry Dunham of Automotive Research Services develops informa-



TORQUE TUBE JANUARY / FEBRUARY 1997



(continued from page 5)

This pickup truck with a Buick logo on the door belongs to Bill Denney (#863) in Dunbogan, Australia. It's parked on "Buick Drive" which is part of Bill's new home. He had a lovely home when I vis-



firewall data plate should have only digits (No "L" or "C" preceding the number). This is true for all 1937 and 1938 open cars as all were assembled in Flint. MI.

On an item mentioned earlier

They do not have to

ited him 2 years ago, but was working on build- in this section about Self-Shifter '38's is that to help members with these

ing a brand new home which has since

been completed.

Bill is restoring a 38-60C Century Convertible Sedan. The photo of it (right) taken in 1946 in San Mateo, California before it was shipped to Australia.

He has restored the instrument panel and painted the horn button and grille and side panel emblems. At

rare vehicles, I will publish a list of owners here in the Torque Tube.

be members of our '37-'38 Buick Club. So if you own one of these rare vehicles or if you know of someone who does. please write to me or you can reach me through E-mail


at (harrylogan@earthlink.net) with the owners name, address, phone number and car model number. I already know of several members with Self-Shifters, so my first list is based on memory:

Fred Graybeal (#1124) 3733 Hulen Park Fort Worth, TX. 76109 (817) 924-1193 38-46

Jim Campbell Jr. (#134) 12188 Forest Meadows Dr. Perry, MI 48872 (517) 675-7150 38-41

Chris Patrick (#1247) 21630 104 Pl. S.E. Kent, WA. 98031 (206) 854-9821

38-41



the bottom of the photo is the frame tag with the number 1-3270553, a Flint built car. Buick only built 208 38-60C's, all of them in Flint, Michigan. So all 38-60C Frame Numbers should begin with a "1" and the Body Number on the

Cover Cars

The cover photo of a 1938 Buick and a modern car gassing up at a period filling station appeared in a General Motors ad in Cigar Aficionado magazine. The ad celebrates the Centennial of the American Automobile. Thanks to *Terry King* (#826) for sharing this with us. The car on the back cover is a black 1938 Buick Century Sedan Model 61 parked in front of a quaint business in Jamestown, California. You can actually go inside and try your hand at "Panning for Gold." Jamestown is located in the Gold Rush Country of Northern California. This area is where the Gold Rush of 1849 took place. Note the man hanging by his neck above the car. This is sometime knows as "Frontier Justice" and occurred frequently during the Gold Rush era.

1937-1938 EASTERN CLUB MEET

Saugatuck, Michigan - June 5 - 7, 1997

Headquarters: Timberline Motel

Blue Star Hwy., Saugatuck, Michigan (1-800-257-2147)

Owners: Herb & Eva Klemm

Weekend rates:

Queen size bed - \$75.00 per night Two double beds - \$85.00 per night

Note:

Rates are \$10.00 less for mid week days. Please make your reservations directly with the Timberline Motel and we suggest you do so as early as

possible to avoid the last minute rush.

Thursday, June 5: Check in at Motel

TY TY TY

Friday, June 6: A tour is being planned to

Gilmore's Red Barn, Hickory Corners, MI.
This is a fabulous collection of cars!

Jesse and Sandy Cahue will host the tour.

Saturday. June 7: Hopefully time will allow for harbor tours, a tour of the

Ferry Keewatin and perhaps time in Hol-

land, Michigan or shopping in Saugatuck. Saturday night we will dine at the "Avalon" Restaurant where you may order from the menu. This region of Michigan is rich in things to do, so you may want to

extend your trip in order to take advantage of this beautiful area. Trust us! Marv and Phyllis

State: Zip
Number in Party: _

Marv Rhynard 15330 Pinehurst Dr. Lansing, Michigan 48906 Phone: 517-484-5188

1937-1938 WESTERN CLUB MEET

Mount Hood & the Columbia Gorge September 19, 20 and 21, 1997



Treat yourself to a trip you'll always Saturday: This is the day for breathtaking remember....enjoy the pristine beauty of Oregon from your special Buick! (Modern cars and hitchhikers welcome too) Your hosts are Doug Nelson and Harry Logan.

Thursday: Southern cruisers traveling north will gather in Salem.

Phoenix Inn 4370 Commercial St. S.E., OR (1-503-588-9220)

· A newer motel with pool and continental breakfast included.

· Mention '37/'38 Club when you make your reservations to get rooms from block reserved for us.

Friday: After breakfast we'll follow Doug and Kay Nelson (#51) to their home.

Tour of their shop, showroom & old cars.

 Cruise old Hwy. 99E to the town of Aurora for antique shopping.

Edgefield Bed & Breakfast, Troutdale, OR (1-800-669-861)

- · Breakfast included
- · 25 acre historic estate
- · Winery, fine dining, gardens
- · Cozy, turn-of-the-century decor

4:00 pm: Southern group joins the Northwesterners with ample time to check out all of the beautiful 1937-1938 Buicks and make new and meet old friends.

scenery! After breakfast, we'll tour the famous Columbia River Hwy to Crown Point for the best view of the Columbia. Cross over to the Washington side to visit Maryhill Museum.not your average museum!

Timberline Lodge, Mt. Hood, OR (1-800-547-1406)

 The lodge was completed in 1937 at the 6,000 ft. level of Oregon's highest mountain. The

lodge was built with tons of native stone, wrought iron and hand-hewn beams of Douglas Fir. President Franklin Roosevelt dedicated the lodge, calling it "a monument to the skill and faithful performance of the workers" who built it. From the lodge you will be able to see snow on the

mountain and see late season skiers on the slopes.

Sunday: After breakfast, we will head down the mountain toward Portland. Those who will be traveling South again can go to the Nelson's in Salem for a catered picnic lunch. If you didn't see all there was to see you can continue the tour of their shop, showroom and old cars.

Come and join '37-'38 Buick Club members for an unforgettable Tour to Oregon.

NOTE:

Eager beavers...it's OK to call now for room reservations! See the next issue for more details.



MY FAVORITE CAR

By Warren Johnson - Santa Ana, CA

cash for a gorgeous 1936 custom deluxe Ford V-8 convertible coupe. It was a real eye-opener and fully loaded with all of the assorted bells and whistles. Yes, it was a real babe-magnet, especially during the summer when I'd drive it around town with the top down.

However, during the rainy winter it was an entirely different story. It was heater-less, drafty and always cold. And water would leak into the front seat where the top clamped to the right- found my "favorite car" at a Buick agency within hand windshield corner post. That's what

happened one rainy night while I was parked in a favorite secluded hideaway. The hormonal juices which have always kept the earth repopulated were now flowing full bore for my amorous love-

muffin and her Ford pilot.

Just as we were getting ready to take off on the main runway, she'd planted her curvaceous right landing gear in that now-liquefied windshield pillar area. As we were now fast reaching the moment of euphoric ascension, the ice-cold water suddenly decided to flow down her retracted appendage and she let out a piercing scream of visceral terror, filling the Ford's now aquatic interior with enough heated expletives to fog up my windshield.

That night turned out to be one short, ruinous and waterlogged romance. And looking back on it now, that was also the night that I realized that I had not as yet found my "favorite car."

After I'd taxied my Ford's version of Noah's

In 1937, I'd earned enough money to pay Ark up to the house where my now ex-date lived, I disgustedly headed for home. I began recalling the memories of my mother's gorgeous 1937 Buick which she had purchased new. I started visualizing its excellent ride, the superb hydraulic brakes along with its powerful engine, yet the ever-quiet and luxurious interior.

> I decided right then and there that my loyalty to dear old Henry was going to transcend to the oh so Generous Motors. Luckily for me, 1

> > a few days. It was a cherry 1937 Buick Sport Coupe they'd sold new and had just been traded in on a new 1938 model. It turned out to be the very best car I've ever owned and, other than the fac-

tory-recommended periodic maintenance, it never cost me a dollar. And whenever I washed this dreamboat, I always noticed that unlike my Ford, its beautiful "Body by Fisher" never leaked!

(ED. Warren Johnson is now nearly 80 years old and lives with his wife in Santa Ana, CA. He worked each summer at the Buick plant in Flint, MI from 1935 up until W.W.II. At that time he met several famous GM engineers such as Charles Kettering and Buick's Chief Engineer Charlie Chayne.

During W.W.II, he was a P-51 fighter pilot and was shot down over Germany and captured. He managed to escape to Spain and back to England. He is a very interesting man with a lot of stories to tell, especially about Buicks, flying and W.W.II.)



THIS CLUB

found abandoned on the street many years before. Dave decided to restore the car, the first one he had ever done. From that decision sprang many things, including the founding of this

Club and a change in his career plans. Dave (#725) 1937 Century 4-Door Trunk Back Sesold his Tire business and became a professional

car restorer.

This is a copy of the letter Dave sent to people who owned 1937 and 1938 Buicks back in 1980 when he was trying to start the Club. He used the Buick Club of America Roster to get most of the names for his mailing list.

Dave had purchased some property on the outskirts of Springfield with the idea of building some apartments as an investment. He had already put in a driveway and four car garage. (see the following page for more photos)

Abandoning the apart-

In 1980, Dave Lewis (#237) had an auto rement project, he put in up a new house on one pair and tire business in Springfield, IL. He in- side of his property, converted the garage to an herited a 1937 Buick sedan that his father had office, and then added a shop to one side of the

> garage. It has a hydraulic lift, a paint room and a place to store and work on cars.

> In the last photo Dave stopped for a moment while working on member John Macmillan's


LEWIS TIRE & AUTO SERVICE


dan Model 61. It's painted

Windsor (light) gray.

The finished car looked beautiful, but was damaged during shipment back to John in Los Angeles and had to be returned to Dave for repairs. It's now repaired and on it's second trip back to Los Angeles from Springfield, IL.

> (ED: Incidentally, John bought this 37-61 sight unseen in Colorado several year ago. After it arrived in Los Angeles, he was surprised to learn that it was the very same car he had owned when he was a boy back in 1957!)








A Buick Fan since CHILDHOOD!

This photo of a young Wayne Chan (#140) Sedan. It's painted Corot Beige with red and a '38 Special Convertible Coupe was taken in the 1960's near Philadelphia, PA. Wayne was attending George Washington University in Washington, DC and loved old Buicks even then.

Here's Wayne today with his beloved 1937 Special Model 48 2-Door Trunk Back

wheels, a 1938 color combination. Wayne knows this is correct because he remembers riding in his father's 1937 Special Sedan with this color combination (probably a late 1937 model year car). Wayne's father was a Buick man too and purchased his car new from Simpson Motors in Palo Alto, CA. in 1937.



HEBILEY

By Lars Gulliksrud (#1013) Oslo, Norway

Yes, I survived Hershey '96. I flew into Baltimore with some Norwegian friends. The next day the rain and storm arrived. We tried to visit the flea market in the afternoon, but it was a total washout, so we returned to our motel in Carlisle, a half hour drive from Hershey. We just looked out the window at the rain!

The next day (Wednesday) turned out to be quite nice. The sun made the muddy flea market roads dry again, and we started walking and searching for parts. I picked up some parts I had ordered from Bob's Automoblia for my '37 Century. I also found a horn and reflector for my 1920 Harley-Davidson motorcycle, but not a speedometer. They are really hard to find. I also found some parts for a '36 Century sedan I'm

working on. Two large suitcases in total!

It was much colder than the last time I visited Hershey, I had to wear my jacket nearly all day. Fortunately there was no more rain during the day. The market was bigger than ever and very crowded at the car corral area, but you can still find lots of nice parts.

On Saturday I got up early to watch the cars drive into the show area. Not many 37-38 Buicks. I only found '37 4-door Special Convertible Sedan and a '38 Special Coupe.

There was also a '37 race track Buick used in the 1950's. This was a strange one fitted with a later (circa 1950) engine, Chevy transmission and a rear end from a Nash. Check that exhaust system!



Steve De Clario (#59) in New Jersey

ver since I graduated college in 1970, I've had a desire to own an old car. I felt that prewar 1930's cars had the most interesting styling and were advanced enough to keep up reasonably well with modern traffic. In 1978 I moved into my own house on Long Island and finally had the means, space and time to seriously consider restoring my own car.

The best styling of affordable cars was to me to be found in the 1936 to 1938 Buicks. After looking at a number of cars I found a '38 Special four door sedan model 41 located just twenty five miles away.

The car had been stored for the past few years but had just been repainted, had a new set of wide

whites tires and a brake rebuild. Otherwise it needed a complete mechanical rebuild and the interior was a disaster, but it started and ran well enough for me to take a chance and

drive it home since it was only 25 miles.

Ominous clouds were over the horizon as I took title to the car and began my trip home with my wife, Nora following me in our 1966 Skylark in case of trouble. On the road, other than very low oil pressure, everything was OK. However, suddenly after about ten miles of 50 mph driving, the temperature gauge began to steadily rise from 170° and it began to rain hard. With the interior getting wet due to dried out window and vent seals, I exited the highway to find a service station.

By now the gauge was pinned at the top and my wife did not see me exit and was no longer with me. I pulled into a gas station and let it cool. After adding water, it wouldn't start since the distributor had become wet from boiling coolant. The repeated cranking had run the weak battery down too low to start. Luckily the gas station had a six volt charger and about a half an hour later I was back on the road.

Only three miles later the gauge was approaching 212° again. Determined to make it home on my own I stopped at another gas station, refilled it and brought along three gallon containers of water with me. I took the Long Island Expressway from this point since there was a rest stop five miles further on from where I could call Nora. Stopping once at an underpass to refill the water again, I made it to the rest stop and called my wife.

After losing me, she had proceeded home expecting me to call. She met me with two garbage

pails full of water in the back of the Skylark and stopping twice more to cool and add water. we made it home. Two hours after starting we parked the Buick in our garage and went

inside to recuperate over some hot coffee.

The events of that day were quickly forgotten, replaced by the excitement of finally owning my own old car. The next day I backed the car out and examined it closely. The odometer was stopped at 40,000 miles but from the condition of the car it was probably at least 140,000 miles. The radiator was completely clogged, the engine smoked like a locomotive, the clutch chattered and the front end had close to 1" of vertical free play (this is no exaggeration since when I rebuilt the suspension the upper pins were so worn they slid right out of the threaded end caps without having to be unscrewed).

When I rebuilt the engine I found that the two compression rings of every piston were either broken into little pieces or pulverized into dust. Most of the pistons had burned channels etched from the top ring down the side to the oil rings with corresponding .02" - .03" deep burn marks on the cylinder walls. It is a testimony to the durability of the Buick engine that with the internal engine conditions I found, the car even started and ran. Not only did it run but aside from the smoke it ran quite smoothly and had decent power.

Over the next five years I rebuilt just about every mechanical part of the car doing all the work except machine shop work myself. I completely replaced the interior and re-chromed all the chrome pieces, with my wife and myself doing all of the work except the chroming. Then for the next ten years I enjoyed the car and won a few second and third place trophies. Due to a change of jobs I recently moved and have not used the Buick for about two years. Now that I am settled in, soon I will finish all the detailing and maybe win a first place.

My car was made in the Linden NJ plant in January 1938 and sold in Homestead, NY. It was owned by a carpenter who worked on the Camp Upton barracks (now Brookhaven Labs) during W.W.II. (I found about two pounds of nails under the rear seat). He used the car for daily transportation until he retired in the late sixties and left it in storage for the next five years. He sold it in 1974 and the new owner had it repainted before selling it to me in 1978. I am the third owner.

Some observations:

OVERHEATING:

When I opened up the engine I found that the water jacket around the rear two cylinders in the block was completely packed with rust and scale which had to be chopped out with screwdrivers and awls. The head was also partially blocked with crud near these two cylinders and the extreme localized heat in this area due to the lack of cooling water caused the head to crack. My theory is that the radiator was not clogged when I picked up the car but as I drove at high speeds the flow of coolant gradually loosened up some of this crud and carried it into the radiator, thus clogging it up.

I had to replace the radiator core since it was corroded enough that any attempt to clean it out by rodding would cause leaks. When I had the radiator re-cored (they used a truck core that has more fins per inch but looks original) I had the shop put a modern fill spout on so I could pressurize the system. I replaced the cylinder head, water pump, hoses and the spring on the water bypass valve. I use a seven pound radiator cap, a 160° thermostat, no overflow recovery (because it shows) and a 50/50 anti freeze mixture.

The temperature gauge normally shows 170°, and even in 100° weather never exceeds 190° except in heavy traffic, but even then it has never overheated. With seven pounds pressure and 50% antifreeze I believe the coolant won't boil until about 240°. If you pressurize your system, make sure your water pump has the newer type shaft seal designed to hold pressure and that all components are in top condition.

FUEL PUMP:

Because of vapor lock problems, I have installed an electronic fuel pump. I used a KEM EFP6 pump, a canister type about the same size as the Big A 95032 fuel filter which I installed between the gas tank and the pump. This pump is solid state, six volts, sealed, costs about \$50.00 and is set for 4-6 pounds pressure. I mounted mine on the inside of the right frame rail under the front door using two of three empty mounting holes that Buick thoughtfully provided in the frame. This provides a completely original appearance.

The pump and filter both mount with a circular strap bracket and I mounted the filter close to the bottom of the frame for easy replacement. I grounded the negative wire to the chassis and ran the positive wire to a toggle switch mounted under the dash and then to an 8 amp fuse picking up the 6 volt source at the ignition switch. I have run at times with the fuel pump on all the time with no problems (my float needle is neoprene tipped) but noticed that the fuel level in the carburetor float bowl rises about 1/16" when the pump is switched on. Perhaps by resetting the float to the specification level with the pump running, the pump can be used continuously.

BATTERY:

I have been using a six volt Sears Commercial battery for the past 9 years and it is still going strong. I had to replace the hold down clamps with slightly longer ones since this battery is about 3/4" taller than the OEM type. This battery has to be ordered from the Sears catalog and is about \$70.00. During the winter months I keep it on a constant trickle charge of about 0.25 amp (uses less than 5 watts of electricity). Although at charge rates of less than 1/ 500 of the amp-hour battery rating the water should not evaporate any faster than normal, it is still a good idea to check the water at least once a month. (ED. Thanks to Steve De Clario (#59) in New Jersey for this story. Steve e-mailed the article (MS WORD) and photo (JPEG format). I encourage all members to submit e-mail WORD articles and IPEG photos. My e-mail address is: harrylogan@earthlink.net. Thanks).

Are your quarantee of so



37

Women drivers were increasing throughout the thirties. This smartly dressed lady is having the technicalities of an AC Klear Klean oil filter explained to her; presumably prior to it being installed on her 1937 Buick Convertible Coupe. It's a Century because it has a chrome strip on the front edge of the top just above the windshield. (Buick Special open cars had a fabric strip instead of chrome).

NOTE: The hubcap with the horizontal BUICK, indicating the photo was posed. The running board trim strip is missing. The inside white wall is dirty while the outside one is clean. The car has accessory fog lights and the center grille guard. The side view mirrors are mounted on the door hinge pin. The Service Manager's name is Harold, written in thread above his pocket. The oil filter's label is pointing right at the camera, also indicating a posed shot. Check how the mechanic rests the hood.

I wonder where "Harold" is going to install the filter as '37/38 Buicks did not have external oil filters.

(Ed. Thanks to **Karl Anderson** (#47) for sharing this photo).

Technical TITPS

CLUTCH FORK BOOT


By Harry Logan (#651)



The boot was sewn to a wire frame that snapped into a rectangular hole in the bell housing. The end of the boot had a hole for the clutch fork to stick through. The purpose of the boot was to keep out dust and dirt etc. Today this boot is missing from many of our cars or if it's still there, it's in poor shape. (below, left)


A black rubberized canvas boot around the clutch fork was installed at the factory on Big Series Buicks (probably Small Series as well). This is what an original boot looked like (above, except the black rubberized coating came off and now only the canvas is left).





I took my original boot and extra wire frame to the local shoe shop. They made two new boots for me out of thin black leather for \$6.00 each. They left it up to me to cut off the pointed end to allow the clutch fork to stick through. The photo above shows the replacement boot. I installed it in about an hour on my '38 Century Coupe. I don't know if the car runs any better, but I like seeing the boot there when I look under my car.

FREEING MANIFOLD HEATER VALVES



Sometimes you'll encounter a stuck manifold heater valve. Studebaker has found that the following mixture is very effective in freeing a stuck valve.


Place approximately two teaspoons full of

baking soda in an oil can which has been filled with kerosene. By applying the mixture as the valve is worked back and forth, a quick release will be obtained. (Thanks to Andy Diem (#852) for this tip).


ADJUSTING '37-'38 AUTOMATIC CHOKES

By Founder Dave Lewis, (#237) Springfeild, IL (Reprinted from the June, 1985 Torque Tube)

Setting the chokes on 37/38 Buicks can be a real challenge. They were difficult to set to say the least. That is why most were converted to manual chokes.



I adjust these chokes using the "Touch System." In other words, you must have the knowledge as to what tension the butterfly choke valve must have, to make the choke work properly. (You learn this by experimentation. It is not an exact science!)




First make sure the choke is in top working condition before trying to adjust it. Remove the side inspection cover on the choke and make sure one or both of the return springs on the two pistons are not broken (a common problem) and that both pistons move freely. You may need a second automatic choke to cannibalize for parts. (ED. You can have broken springs remade. I had some made by MSC, PO Box 13334, Pittsburgh, PA. 15243. Phone: (412) 341-8989. Ask for their catalog.) After this is completed, you're ready for the adjustment.


You must remove the carburetor and choke from



the car. You can mount the assembly in a vise by the carburetor base, leaving the choke attached. With the unit in a cold state and the choke drive cable attached, you simply feel the resistance the choke valve has. It should of course be in the closed position at this point.



On the bottom, after the outer heat tube is removed, you will see a coil spring with an Allen head set screw. This is how you make the adjustment to the butterfly on the top of the carburetor. Because of it's location, you cannot make this adjustment while the carburetor is on the car. Since this is not a 100% accurate means of adjustment, you might have to remove the unit from the car several times to get it right.



There is also a small adjustment on the side of the choke inspection plate that can be made with the carburetor installed on the car. It only covers a small range and is for minor seasonal adjustments for leaner or richness as the temperatures change.




ORIGINAL BUICK GLASS

By Harry Logan (#651)



This close-up of original 1938 Buick glass has the manufacturer's initials **L.O.F.** inside a shield with the words *Safety PLATE Glass* and the date code below. L.O.F. stands for Libby-Owens-Ford. The glass in the photo is on a 1938 Century Sedan. All the window and windshield glass date codes on this car are either **10/37** or **11/37**, so the car was probably made in December of 1937.

If you replace your original with modern glass, you'll loose this logo and the date code. Most restorers don't worry about this. If you are looking for originality, you can buy glass with



the L.O.F. logo and date code. When ordering the glass, tell the glass provider what date code you want.

One company that does this is OEM Glass Inc., PO Box 362/Highway 9 East, Bloomington, IL 61702. Phone (309) 662-2122 or (800) 283-2122. They accept VISA and M.C. credit cards.

1937 Buick glass has a different pattern. It has a shield or box with the initial **LOF** inside. The word **SAFETY** in capital letters is above the shield and the word **PLATE** is below. Under that is the date code such as **3-37**.

WHY DO THE WHEELS TURN

By Dave Paulisin (#704) - Michigan

"I had my 1937 Roadmaster rear axle raised and on jack stands in my garage. The front wheels were on the ground. I found that when the motor was running and the transmission in neutral, my rear tires would rotate counterclockwise. I could stop the rotation with my hand on one tire but the opposite tire would rotate. There was no noise in the rear end. Depressing the clutch pedal would stop all tire rotation. The car will not move on level ground when all four tires are on the ground with the engine running and the transmission in neutral.

I am puzzled. I cannot explain the rear wheels moving. What causes this? My mechanic

"I had my 1937 Roadmaster rear axle raised friend told me it was normal but did not explain on jack stands in my garage. The front why. Maybe one of our members can help?"

(Ed.I put this question to **Don Micheletti** (#250). The rear wheels rotate when they're off the ground and the transmission in neutral because of the viscosity of the transmission oil. When the motor is running and the transmission is in neutral, the main drive gear (input) to the transmission is turning because the motor is running. It is coupled to the transmission's output gear and to the drive shaft by the thick transmission oil. This causes the rear wheels to turn if they are off the ground but this is normal. For more details see the diagram at the bottom of page 21, opposite)

MAKING A GOOD MANIFOLD TO TAILPIPE SEAL

Technical TIPS Buck

By Harry Logan (#651)






These are some of the exhaust gaskets I purchased at local auto parts stores. The are used to seal the manifold to the exhaust pipe. I have had difficulty getting a good seal. Most of the exhaust would go out the tail pipe, but some would escape into the engine compartment. This small leak would also increase the noise level in the car which annoyed me. After trying various gaskets, I got the best seal using the gasket that is flat on one side with metal tabs that hold it to the exhaust valve body.

I had to bend the metal tabs slightly to get a good tight fit. The tapered side of the gasket fits into the flanged end of the tail pipe. I found I could get a better (tighter) seal if I replaced the two original 2" long x 3/8-24 hex head bolts that hold the tail pipe to the exhaust body with the strongest bolts I could find. I used Grade 8 bolts which have a golden color. They have a tensile strength of 150,000 lbs. (Grade 2 has a tensile strength of 85,000 lbs and Grade 5 120,000 lbs). Now I don't have an exhaust leak anymore.

WITH THE CAR IN NEUTRAL?



WELCOME

Members

John Hart (#1238) 1894 Chatham Dr. Troy, MI 48084 37-44

Anthony Geraci (#1239) PO Box 28 Bradford, RI 02808 37-47

James Adkins (#1240) 4694 Royalwood Rd. N. Royalton, OH 44133

Bill Paulisin (#1241) 24858 Wilmot Eastpointe, MI 48021 Helser's Metal Finishing, Inc. 980 E. 200N Warsaw, IN 46580 37-46

Monte Anderson (#1243) 101 Pine Forrest Lane Chattanooga, TN 37415 38-48

Bennie Gibson (#1244) 7200 Old Mill Run Fort Worth, TX 76133 38-46C

John Sullivan Jr. (#1245) 343 El Brillo Way Palm Beach, FL. 33480 37-66C McL Paul Delucchi (#1246) 470 Lombard St. San Francisco, CA. 94133 38-41

Chris Patrick (#1247) 21630 104 Pl. S.E. Kent, WA. 98031 38-41

Tim Franko (#1248) 5016 E. Pleasant Valley Rd. Independence, OH 44131 38-61

Delbert De Young (#1249) 140 Seaview Ct. #806S Marco Island, FL 34145 37-66S 38-91

Parts FOR SALE

• 1937 PARTS	
Parking lights with pot metal (pot metal fair to good)	\$20.
Trunk lid light	\$20.
Water temp guage	\$65.
Gas Guage	\$20.
Horn button, plastic bad	\$10.
Trunk tire hold down bracket	\$15.
Bolts for bumper guards	\$10. each
Hood hinge (60)	\$75.
Steering column (60)	\$35.
Rear leaf springs, used but good (40-60)	\$85. set
4-Door sedan body stainless with small cowl stainless (40-60)	
Front bumper (40-60)	
Drivers side rear fenders (40-60)	\$45
60-80-90 series transmission case	\$45
Engine, 60-80-90 series	
60-80-90 series transmission pilot shaft, used but good	\$45
• 1937/1938 PARTS	620
Map light switch, used	\$20.
Buick Hose clamp set	\$15. set

(continued from page 22)	6110
NOS Rocker arm shaft, with bushings, 40 series	
Hydraulic lifters, cam, rocker assembly, push rods etc. 60-80-90	\$225. set
Sidemount emblems, original	\$95. set
Sidemount emblem, repro-brass	\$25. set
Front convertible radiator brackets	
Rebuilt distributor	\$65.
Metal brace between trunk shelf wood	\$20.
Hump back trunk hold open arm	\$45.
Water pump, rebuildable	\$15.
Bracket that holds exhaust pipe to the engine	\$25.
Generator, (40)	
Intake and Exhaust manifold, (40)	\$45.
Thermostat housing, (40)	
Wing vents (front, chrome in good condition, (40-60)	\$45. set
Rear wing vent handles, chrome in good condition, (40-60	\$25 set
Door hinges, (40-60)	\$20 each
Sun visor brackets, very good condition, 40-60	\$25
Sun visor brackets, very good condition, 40-00	¢15
CENTURY wheel brake cylinder, needs rebuilding (60)	635
Rear motor mounts, core only, (60)	
Transmission center main shaft, used but good, (60-80-90)	543.
Transmission second speed gear, used but good, (60-80-90)0	
Generator, (60-80-90)	
Starter, (60-80-90)	
Air cleaner, (60-80-90)	\$35.
• 1938 PARTS	
Bumper guards, straight	\$45. each
Bumper guards, bent a little	\$25. each
Oil guage, used	\$30
Gas gauge, used	\$30
Amp gauge, used	\$30
Temperature guage	
Grille, right and left side, pitted	\$25. set
Battery box with hold-down bracket	
Hood stainless hinge, like new, (40)	
Hood, good cindition, (40)	
Transmission, (40)	
New fuel pump kit, (40)	
Rear sway bar, (40-60)	
Bumper, front, no hole in the center, (40-60)	
Engine, BIG SERIES	
All prices plus shipping. Call between 9 AM and 1 PM EST Monday to Friday or anytime of	n Saturday and Sunday.
David Bylsma (#117)	
7802 Chevalier Ct.	
Severn, MD. 21144	
(410) 551-7236	

• 1938 PARTS - SPECIAL Engine, transmission & Rear End......\$200. for all Making Street Rod so these parts are not needed Gary Randolph

Parts FOR SALE

• 1937 & 1938 PARTS

• 1937 & 1938 PARTS	
Parting '37 & '38 Buicks. The following is just a portion of the parts availab	le. Call with your needs.
1937 Parts	
Grille, no cracks, good chrome	\$350
Master heater, complete	\$75
Deluxe heater, complete	
40 & 60 complete steering linkage	\$75.
Coupe & 2 Dr. Sedan side stainless, complete sets	\$75.
CENTURY brake & clutch pedal assembly	
Buick 8 clock hole filler	
ROADMASTER dome light	
Bumper guards	
CENTURY front coupe seat, very nice original	
SPECIAL NOS flywheel and ring gear	
SPECIAL generator 918G	\$75
CENTURY radiator	
SPECIAL radiator	
SPECIAL complete manifold, AA-1 carb, starter switch, linkage and	air cleaner \$350
Rear springs 40 & 60, good condition	\$100 pair
Radio delete plates	c15
Hubcaps	
Small & large series throttle linkage	
BIG SERIES rocker assemblies	543.
Fender lights	
Fender lights.	\$05. pair
Trunk lights, complete	
Pair lights with lenses, all series	350.
Wiper transmissions	\$50. pair
SPECIAL manifold	\$75.
BIG SERIES intake manifold only	
Radio dash plates	\$20.
Headlights, complete. Excellent	\$200. pair
Throttle cable	\$20.
SPECIAL transmission	\$100.
SPECIAL splash pans	\$40. pair
ROADMASTER runningboard stainless. New with clips	
CENTURY hood	
Headlight switch	\$20.
Radio grilles	\$15.
Wiper motors	\$15.
Trunk hold-up arms	
Sun visors	
Bumpers	
Bumper arms	
Horn button	
Steering wheel	\$50
Contact shiples and have	

 (continued from page 24)

(continued from page 24)	
* 1938 PARTS	
Defroster motor & dash vents	
Trunk emblem	\$35.
40 & 60 sedan trunk lid, no rust	\$75.
Breather tubes	\$10. each
Trunk hold-up arms	
734Z starter with solenoid	\$50.
Horn button	\$10.
Radio hole plugs	
SPECIAL hood lettering.	\$20. pair
Defroster ducts	
Wiper transmissions	
Rear license plate stand, bracket & light for sedan	\$45.
Rear license plate stand, bracket & light for a coupe	\$65.
Bumper guards	\$20.
Pair lights, complete	
Assist straps with screws	
Throttle cable	
SPECIAL radiator	
Battery tray	
Generator	
SPECIAL manifold, complete	
SPECIAL hood sides & tops	
Gas tank door	
Sedan trunk weather strip, new rubber	\$25
Grille, no cracks, minor pitting	\$200
SPECIAL rods & pistons, set of 8	\$75
Fender lights	
SPECIAL front fenders, very good condition	
Gauge cluster with working temperature gauge	
Hood ornament, minor pitting	
CENTURY hood bar, straight & good for chroming	
CENTURY hood sides and tops	530. each
• 1937-1938 PARTS	¢15
Map light switches	
Small series spark plug covers	
NOS Large Series water pump	
SPECIAL air cleaner	
SPECIAL running boards, clean & straight	
SPECIAL flywheel, excellent teeth	
Rear fender splash aprons	
BIG SERIES manifold ends	
16" beauty rings	
2 Door rear ash trays	
Headlight bezels	
Trunk hinges	
SPECIAL oil pump	
Front arm rests	
40 & 60 rear vent windows, need plating	
Four 15" beauty rings	
Sidemount locks with keys	\$75. pair

6	continued from page 25)
	Rear view mirrors
	Steering column support with ignition, keyed\$35.
	SPECIAL rear motor mounts
	CENTURY rear motor mounts
	40 & 60 4 dr. sedan doors
	Front vent window frames & mechanisms
	Dave Tacheny (#997), 11949 Oregon Ave. N., Champlin, MN 55316
	(612) 427-3460
	• 1937-1938 SPECIAL PARTS
	Used Rear Brake Drums\$30. each
	Brake shoes for 4 wheels (8 shoes). Need relining. 1 3/4" wide \$30.
	Brake Backing Plate for right rear wheel
	NOS sleeve that holds pinion gear bearing. Fits 1936 to 1955 Specials. P/N 1336942 \$30.
	NOS Transmission Reverse Idler gear. P/N 1283878\$50
	NOS Delco-Remy Starter Armature. P/N 823881 in original box\$40
	NOS 4.44 Ring and Pinion Gear set in original carton
	Used Torque Ball with brass bushing\$25
	1937 chrome radio grille with separate wire mesh screen. Needs rechroming
	Rechromed Left '37/'38 Trunk Back Sedan Trunk hinge
	'38 Hood ornament, needs rechroming
	[[
	SPECIAL Engine Splash Pan, right side only
	'37-'38 Big Series "X" fan, 18" diameter\$25
	'37-'38 Small Series "X" fan
	Pair of restored 1937 Minnesota license plates
	Pair of 80/90 Series sidemount retainer plates. Fits in center of rim
	to hold sidemount tire in place\$35. pair
	AA-1 carb for '37 Special. Missing throttle linkage. Good for parts \$20.
	Harry Logan (#651), 1005 Rilma Lane, Los Altos, CA. 94022
	(415) 941-4587 PST
	• 1937 ROADMASTER 80 SERIES PARTS
	Pair of recast trunk hinges, 80 Series, need refinishing
	4 Stainless door latch plates
	2 ROADMASTER hood louvers, left and right\$35. each
	Front seat frame, adjuster. Excellent wood, no springs
	Running board, driver's side, rubber chipped, need recovering,
	some surface rust. No rust out
	Sedan floorpan. Use for convertible sedan. Rust free.
	Spotwelds drilled out or remove
	Waterpump, NOS
	Inside window frames
	• 1937 ROADMASTER CONVERTIBLE SEDAN PARTS
	Recast convertible top center hook. Mounts on divider bar of windshield
	Recast bracket for wood header to mount mirror
	• 1937 PARTS - ALL SERIES
	Front nose section to hold grille. Bare, no air baffle

continued from page 26)	
Vacuum starter switch, NOS	\$50
Delco Remy Voltage Regulator, NOS	
Inside dash light	\$10
Radio, rebuilt	\$350
Radio, used	\$100
1937 SPECIAL PARTS	
Rechromed front bumper or trade for Roadmaster bumpers	\$150
Under seat battery cover	\$15
Misc. inside window frames	.\$4. to \$6. each
NOS Stromberg carb kit plus AA-1 NOS carb	\$150
NOS in box, Heavy Duty oil bath air cleaner 40 series	\$75
Set of radiator support rods	\$20
NOS pair of trunk hinges	\$135
Pair of trunk hinges, 1 possibly NOS	\$100
NOS water pump repair kit	\$25
NOS pushrod	\$9
Transmission lever shifter parts kit	\$15
• 1938 PARTS	
Front bumper, 2 brackets, 1 guard. Straight but needs to be re-chromed	\$120
All Parts Plus Shipping	
David Powers (#894), 27732 Paseo Barona, San Juan Capistrano, CA 920	623
(714) 493-1199	
• 1937-1938 PARTS (all NOS or NORS)	67.0
Ignition rotor, NORS	
Ignition rotor, NORS	\$8.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS	\$8.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS	\$8.0 \$2.0 \$6.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS	\$8.0 \$2.0 \$6.0 \$10.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60)	\$8.0 \$2.0 \$6.0 \$10.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60) Lower steering knuckle support pin (80-90)	\$8.0 \$2.0 \$10.0 \$30.0 \$30.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60) Lower steering knuckle support pin (80-90) Big Series (60-80-90) clutch pressure plate (plate only)	\$8.0 \$2.0 \$10.0 \$30.0 \$15.0 \$35.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60) Lower steering knuckle support pin (80-90) Big Series (60-80-90) clutch pressure plate (plate only) Transmission main drive bearing	\$8.0 \$2.0 \$10.0 \$30.0 \$15.0 \$35.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60) Lower steering knuckle support pin (80-90) Big Series (60-80-90) clutch pressure plate (plate only) Transmission main drive bearing Right front shock absorber (40-60)	\$8.0\$2.0\$10.0\$30.0\$35.0\$35.0\$35.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60) Lower steering knuckle support pin (80-90) Big Series (60-80-90) clutch pressure plate (plate only) Transmission main drive bearing Right front shock absorber (40-60) Rear wheel bearing (40-60)	\$8.0\$2.0\$10.0\$30.0\$35.0\$35.0\$35.0\$35.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60) Lower steering knuckle support pin (80-90) Big Series (60-80-90) clutch pressure plate (plate only) Transmission main drive bearing Right front shock absorber (40-60) Rear wheel bearing (40-60) Rear wheel bearing inner race (40-60)	\$8.0\$2.0\$10.0\$30.0\$35.0\$35.0\$35.0\$35.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60) Lower steering knuckle support pin (80-90) Big Series (60-80-90) clutch pressure plate (plate only) Transmission main drive bearing Right front shock absorber (40-60) Rear wheel bearing (40-60) Rear wheel bearing inner race (40-60) 1937 SPECIAL PARTS	\$8.0\$2.0\$6.0\$30.0\$35.0\$35.0\$35.0\$85.0\$85.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60) Lower steering knuckle support pin (80-90) Big Series (60-80-90) clutch pressure plate (plate only) Transmission main drive bearing Right front shock absorber (40-60) Rear wheel bearing (40-60) Rear wheel bearing inner race (40-60) 1937 SPECIAL PARTS Universal joint (40)	\$8.0\$2.0\$10.0\$30.0\$35.0\$35.0\$35.0\$35.0\$85.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60) Lower steering knuckle support pin (80-90) Big Series (60-80-90) clutch pressure plate (plate only) Transmission main drive bearing Right front shock absorber (40-60) Rear wheel bearing (40-60) Rear wheel bearing inner race (40-60) * 1937 SPECIAL PARTS Universal joint (40) Transmission 2nd & 3rd speed sliding sleeve (40)	\$8.0\$2.0\$6.0\$10.0\$30.0\$35.0\$35.0\$35.0\$85.0\$85.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60) Lower steering knuckle support pin (80-90) Big Series (60-80-90) clutch pressure plate (plate only) Transmission main drive bearing Right front shock absorber (40-60) Rear wheel bearing (40-60) Rear wheel bearing inner race (40-60) * 1937 SPECIAL PARTS Universal joint (40) Transmission 2nd & 3rd speed sliding sleeve (40) Transmission 2nd gear (40)\$35.00	\$8.0\$2.0\$6.0\$10.0\$30.0\$15.0\$35.0\$20.0\$85.0\$85.0\$30.0\$20.0
Ignition rotor, NORS	\$8.0\$2.0\$6.0\$10.0\$30.0\$15.0\$35.0\$20.0\$85.0\$85.0\$30.0\$20.0
Ignition rotor, NORS	\$8.0\$2.0\$6.0\$10.0\$30.0\$35.0\$35.0\$85.0\$85.0\$80.0\$90.0
Ignition rotor, NORS	\$8.0\$2.0\$6.0\$10.0\$30.0\$15.0\$35.0\$20.0\$85.0\$85.0\$20.0\$90.0
Distributor cap, NORS	\$8.0\$2.0\$6.0\$10.0\$30.0\$15.0\$35.0\$20.0\$85.0\$85.0\$20.0\$90.0
Ignition rotor, NORS	\$8.0\$2.0\$6.0\$10.0\$30.0\$15.0\$35.0\$20.0\$85.0\$85.0\$20.0\$90.0
Ignition rotor, NORS. Distributor cap, NORS. Ignition condenser, NORS. Ignition points, NORS. Headlight dimmer switch, NORS. Lower outer pivot pin kit, (40-60). Lower steering knuckle support pin (80-90). Big Series (60-80-90) clutch pressure plate (plate only). Transmission main drive bearing. Right front shock absorber (40-60). Rear wheel bearing (40-60). Rear wheel bearing inner race (40-60). * 1937 SPECIAL PARTS Universal joint (40). Transmission 2nd & 3rd speed sliding sleeve (40). 1937 Engineering Story, 26 pages. * 1938 SPECIAL PARTS Transmission 2nd & 3rd speed sliding sleeve. Rear coil spring (40C, 41, 47, 48).	\$8.0\$2.0\$6.0\$10.0\$30.0\$15.0\$35.0\$20.0\$85.0\$85.0\$20.0\$90.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60) Lower steering knuckle support pin (80-90) Big Series (60-80-90) clutch pressure plate (plate only) Transmission main drive bearing Right front shock absorber (40-60) Rear wheel bearing (40-60) Rear wheel bearing inner race (40-60) * 1937 SPECIAL PARTS Universal joint (40) Transmission 2nd & 3rd speed sliding sleeve (40) Transmission 2nd gear (40)\$35.00 1937 Engineering Story, 26 pages * 1938 SPECIAL PARTS Transmission 2nd & 3rd speed sliding sleeve Rear coil spring (40C, 41, 47, 48) Please add 15% for UPS shipping Robert Graves (#1136) 56 Darthmouth St.	\$8.0\$2.0\$6.0\$10.0\$30.0\$15.0\$35.0\$35.0\$20.0\$85.0\$30.0\$20.0\$20.0
Ignition rotor, NORS Distributor cap, NORS Ignition condenser, NORS Ignition points, NORS Headlight dimmer switch, NORS Lower outer pivot pin kit, (40-60) Lower steering knuckle support pin (80-90) Big Series (60-80-90) clutch pressure plate (plate only). Transmission main drive bearing Right front shock absorber (40-60) Rear wheel bearing (40-60) Rear wheel bearing inner race (40-60) * 1937 SPECIAL PARTS Universal joint (40) Transmission 2nd & 3rd speed sliding sleeve (40) Transmission 2nd gear (40)\$35.00 1937 Engineering Story, 26 pages * 1938 SPECIAL PARTS Transmission 2nd & 3rd speed sliding sleeve Rear coil spring (40C, 41, 47, 48) Please add 15% for UPS shipping Robert Graves (#1136)	\$8.0\$2.0\$6.0\$10.0\$30.0\$15.0\$35.0\$35.0\$20.0\$85.0\$30.0\$20.0\$20.0

EXTRA! EXTRA! BACK ISSUES NOW AVAILABLE

THE FOLLOWING BACK ISSUES ARE AVAILABLE FOR \$4.00 EACH POSTPAID.

- 1991-1992 VOLUME X NUMBERS 1 THROUGH 9
- 1992-1993 VOLUME XI NUMBERS 1, 2, 4, 5, 6 AND 7
 - 1993-1994 VOLUME XII NUMBERS 2, 4, 5 AND 6
- 1994-1995 VOLUME XIII NUMBERS 1 THROUGH 6
- 1995-1996 VOLUME XIV NUMBERS 2 THROUGH 6

Please make your checks payable to:

The 1937-1938 Buick Club 1005 Rilma Lane Los Altos, CA. 94022 USA

Parts WANTED

WANTED:

For 1937 ROADMASTER:

- · Front bumper
- · Front bumper brackets
- Rear gravel shield.
 Fits inside rear bumper
- · Rear bumper brackets
- · Ashtray for rear seat arm rest
- · Arm-rests for rear seat area
- Robe rail with 2 piece socket assembly on each end
- · Seat cushion springs
- · Front seat upper back
- · Rear seat lower cushion

Convertible Parts:

- ·Inside visors or brackets
- Window frame forvent window.
 Convertible only. Metal frame to hold vent glass on front door
- · Convertible top parts
- Any 1937 accessories or unusual parts
- Sidemount covers or possibly front fenders complete
 David Powers (#894)
 27732 Paseo Barona
 San Juan Capistrano, CA 92623
 (714) 493-1199

WANTED:

1938 PARTS NEEDED:

- Fast Back Sedan Trunk Lid (40 or 60)
- · Splash Pans for CENTURY
- · Front License Plate Holder
- Rear Seat Arm Rests from 40 or 60 Series Car.
- BIG SERIES Fly Wheel Ring Gear (156 teeth)
- · Windsheild Wiper Transmission
- · Radio Grill

For BIll Denney (#863) in Australia

Contact:

Harry Logan (#651) 1005 Rilma Lane

Los Altos. CA 94022

(415) 941-4587

WANTED:

1938 PARTS NEEDED:

- ROADMASTER Fast-Back
 Sedan Trunk Lid for Model 80C or 87
 or CENTURY or SPECIAL Fast-Back
 Trunk Lid.
- ROADMASTER running Boards and Moulding.
 James Adkins (#1240)
 4694 Royalwood Road
 N. Royalton, Ohio 44133
 (216) 582-4365

Gars FOR SALE

FOR SALE:

 1938 ROADMASTER Convertible Sedan Model 80C with sidemounts. Older amateur restoration. Driven extensively in the 1980's. Garaged for restoration in 1992. Complete with many accessory items.

\$20,000.00

Ed DePouli (#310) (201) 767-3168 home (New Jersey) (914) 651-1313 work



FOR SALE:

 1937 SPECIAL Convertible Sedan Model 40C. Body-off restoration. Rebuilt motor, transmission, rear end. New brakes, front end, wiring, leather interior, chrome, stainless. Has radio, heater, map light, clock, sidemounts, Trippe lights and accessory front grille guard.

Priced right. Call:


Sal Biagini (#566) (718) 847-5869 after 6 pm EST

FOR SALE:

 1938 ROADMASTER Phaeton Model80C California car. No rust ever. Recent cream lacquer paint. New running boards, chrome, wiring. New top in a box. Wide whitewall tires. Recent engine rebuild.
 Sidemounts. Needs finishing.

\$25,000.00

Jim Fuller (#737) Santa Barbara, CA (805) 969-4538



FOR SALE:

• 1938 SPECIAL 4-Door Convertible Sedan. 60% restored. Many new parts. Excellent body with clear title. Located in Maryland. Delivery negotiable.

\$10,00.00

David Bylsma (#117) 7802 Chevalier Ct. Severn, MD. 21144 (4110) 551-7236

FOR SALE:

• 1937 Coupe

2,000 hours in restoration. Rebuilt to 1937 condition. Radio, heater. 800 miles on rebuilt engine. Lacquer paint. Maroon/ beige. Bedford cord upholstery. Many NOS parts. Send \$3.00 for photo set.

\$16,900.00

L. Piniuta 19 D'Arcy Street Toronto, Canada M5T 1J8 Tel: (416) 977-2501 FAX (416) 977-0016

FOR SALE:

 1937 SPECIAL Slant Back 4-door Sedan Model 47. Solid body. Good running condition.

\$5,500.00 OBO

Virginia McNamara (630) 832-9345 Illinois

Matley Woodgraining Service

13912 S.E. 241st St. Kent, Washington 98042



Shop (206) 630-2008 Res. (206) 630-8887

"The Crowning Touch To A Quality Restoration"




J.B. Donaldson Co.

2533 W. Cypress St. Phoenix, Arizona 85009 (602) 278-4505



Thru 1953 \$2.00 for Brochure, <u>Must</u> Specify Year



RESTORATION



SERVICES

Running Board / Rocker Moldings

1934 thru 1940

SSAE for Information

BUICK RESTORATION SERVICES

P.O. BOX 442, PERRY,

MICHIGAN

48872



1927 TO 1953

WIRING HARNESSES

AUTHENTIC REPRODUCTION
WIRING SYSTEMS THRU 1953
HAND CRAFTED WITH THE
FINEST MATERIALS
EACH SUPPLIED WITH:
LIMITED WARRANTY
INSTALLATION INSTRUCTIONS
SCHEMATICS

ALSO OFFERING: WIRING SUPPLIES CATALOG OR INFORMATION S5



BOX 435 WAYNE, PA. 19087

FRONT FLOORMAT 1937-38 All Models Black or Brown FF-378.....\$195.




AUTOMOBILIA (805) 434-2963

1937-38 BUICK




DOOR W	EATHERSEAL-SPONGE	
Glue-in	nDW-378	\$1.70 ft.
Clip-in	DW-80	\$3.40 ft.
Clips	WC-80	\$.60 ea.



TRUNK SEAL-SEDANS, 1/2' Wide;		
Ser. 80-90TW-371	\$31.	50
Sedans. 3/4' Wide;		
Ser. 40-60TW-371S	\$31.	50









SHIFT BOOT, 1937-38 Series 40 Only! Black \$ 9.75 Brown.....\$14.50

Series 80-90 Black

DOOR SILLS: Trim To Fit

2-Door \$62/pr. 2Door \$93/set.

GLOVE BOXES; \$27. ea.

PARKING LIGHT LENS...... \$17.50 ea

CARB. KITS: CARTER CK-360C \$26.00 STROMBERG...... CK-37XS \$26.00

TORQUE BALL SEAL KIT. All Models TBK-343\$26.00

VISOR "VANITY" MIRROR, VM-379 \$27, ea.




LICENSE PLATE FRAMES. Chromed Brass LF-333P.....\$60. Pair

FRONT END PARTS For 40-60 Series; Upper Outer Kit..... \$39.00 King Pin Sets......\$35.50 Lower Inner Bushings......\$20.00 Tie Rod End.....\$27.00





EXHAUST MANIFOLDS 1937-38 Series 60-80-90 ENDS \$180. CENTER \$182. VALVE BODY \$195.

RUNNING BOARD INSULATORS, 1937-38 All Models, ALL NEW MATERIAL! 4 Needed Per Running Board.



HOOD REST PADS, 1937-38 6-8 Per Car.





OUTSIDE DOOR HANDLE CHROME and RUBBER GROMMETS. 1 FERRULE & 1 GROMMET Per Set. 1937...... DGF-296...... \$5./Set 1938...... DGF-380...... \$5./Set



1938 TRUNK HANDLE/LIGHT MOUNTING SEAL \$8.75

MOTOR MOUNT, FRONT, All Models ROUND PADS SP-338 ... \$10. pr. MOUNT......MM-347..\$29. ea.

TRUNK HINGES for 40-60. Chrome Plated \$150. pr.

1937 HUB CAPS. All Ser HC-37 \$60. ea. WHEEL Beauty Rings. 15' or 16' \$89./Set of 4 1937 or 38 HOOD ORNAMENT......\$85.

SOME OTHER ITEMS WE STOCK: BEARINGS. DECALS, ENGINE PAINT, DECALS, SHOP MANUALS, PARTS BOOKS, BODY BOOKS and MORE. SHIPPING;10%, max.\$9, min. \$4, Prepaid, C.O.D. Add \$5,

BOB'S AUTOMOBILIA BOX 2119 ATASCADERO CA. 93423 TELEPHONE (805) 434-2963 .VISA- MASTERCARD-DISCOVER or C.O.D. CATALOG #43 \$4.00 - PHONE ORDERS - (Write For Catalog)



















Buick Upholstery and Top Kits

Since 1977




HAMPTON

Phone 508-388-8047 (Coach)




P.O. Box 6, 6 Chestnut Street, Amesbury MA 01913

New for 1937-1938 BU



New stainless side mount emblems. Includes mounting screws on back side. \$62.50 each



New stainless convertible top latches & header hooks for 40 & 60 series Coupe & Phaeton (6 peice set) \$365.00



MAPLELEAF FABBRICATION & MACHINE

13912 SE 241st. Street, Kent, WA 98042 206-630-2008

© Torque Tube 1996-199